

# IMS-4000E Software & Firmware Revision History

#### **Windows Workstation Client Software**

**ConsoleView Management Software 3.0.35** 

### **Equipment Firmware**

BootSys	6.05
IMS4k OS	4.26
System Support	5.06
Voice	2.13
Node Firmware	1.80
Dry Contact Node Firmware	1.80

Release Date July 22, 2022

#### **IMS-4000E Software & Firmware Revision History**

#### **ConsoleView**

**Version 3.0.35** (January 27, 2021)

• Fixed an issue when selecting the sensor sub-type as 'Air Flow Sensor'.

Version 3.0.34 (July 10, 2020)

• Added additional options to e-mail settings to manually configure STARTTLS, TLS, and port number. Requires host firmware 3.41 or greater.

#### IMS4k

Version 4.26 (6/17/2022)

• Fixed an issue where newly added IP Alarms would not be enabled

Version 4.25 (03/18/22)

- Fixed an issue where the SNMP agent could be starting even when disabled
- Corrected order of SNMP Trap variables.

Version 4.24 (02/08/22)

• Corrected an issue causing distorted speech during telephone calls

**Version 4.23** (01/28/22)

• Corrected an issue that prevented node network configuration through web page

Version 4.22 (01/18/22)

• First release version

## **BootSys**

Version 6.05 (7/18/2022)

• Fixed network configuration issue to allow prefixes other than 24-bit

**Version 6.04** (1/18/2022)

• First release version

## **System Support**

Version 5.06 (1/17/2022)

• First release version

### **VoiceWare**

**Version 2.13** (4/17/2009)

• First release version

## **Node Firmware**

**Version 1.80** (4/30/2020)

• First release version

## **Dry Contact Node Firmware**

**Version 1.80** (4/30/2020)

• First release version